

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD, West Division - Araria

Name of Block/Road :- Araria | 1026 - Pategma to Sahasmat Birri Pool (VR-26)
Kauwacher ghat at Parmam river

A. For Road

1. Damage Location/Chainage :- 0.450 km

2. Damage Length :- 74.50 m

3. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage :-
(iii) Only Flank Damage :- Flank damage

whether traffic fully/Partially obstructed :- partially

4. Details of Restoration :-

(i) Material Being Used in Restoration :- (Ocal sand, Bamboo, Brick Ball, EC Bags etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with trolley, JCB, Roller, etc

(iii) Restored Length In open Area :- 74.50 m
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector
(Official Seal)

Cy 20
14/11/24
m