

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- E.E. R.W.D. BARSOI

Name of Block/Road:- RUPALI / Viveka Chowk to Balia via Malpur

A. For Road

1. Damaged Location/Chainage:- 1.90 KM

2. Damage Length:- 0.235 KM

3. Nature of Damage (Length)

(i) Breach:-	✓
(ii) Crust Damage:-	✓
(iii) Only Flank Damage:-	✓

Whether traffic fully/Partially obstructed:-

4. Details of Restoration:-

(i) Material Being Used in Restoration :- Brick Bats

(ii) Equipment/Tools Being used in restoration works :- JCB, Tractor

(iii) Restored Length

(i) In open area :-	✓
(ii) In habitation Area :-	✓

(iv) If Restoration work done in habitation Area given Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :- N/A

(2) No. of Span Damage:- N/A

(3) Length of Span:- N/A

(4) Nature of Damage (Pier/Abutment/Wing wall/Approch Road Damage):- N/A

(5) Details of Restoration:-

(i) Material being used in restoration:- N/A

(ii) Equipment/Tools being used in restoration works:- N/A

(iii) Restored Length :- N/A

Overall Grade of Restoration works (Satisfactory/Unsatisfactory):- Satisfactory

M. Jha
28/11/24
JE

S. Jha
28/11/24
AE

Signature of Inspector
(office Seal)

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंखल, बारसोई, कटिहार