

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division Anarua	
Name of Block/Road :- Tokihot/Matiyari Magra PMGSY Road Idgah to Majgama ghot Jhokur Tola	
A. For Road	
1. Damage Location/Chainage :- 1.4 km, 1.5 km, 2.49 km	
2. Damage Length :- 94 m	
3. Nature of Damage (Length Wise)	(i) Breach :- Breach Damage
	(ii) Crust Damage :- Crust Damage
	(iii) Only Flank Damage :-
whether traffic fully/Partialiy obstructed :- fully	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Local Sand, EC bags, Brick bats, Bamboo etc	
(ii) Equipment/Tools Being Used in Restoration Works :- Roller, JCB, Tractor with Trolley	
(iii) Restored Length	In open Area :- 94 m open Area
	In habitation Area :-
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :- 1.4 km	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage) :- Approach Road Damage	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :- Local Sand, Brick bats, bamboo, EC bags	
(ii) Equipment/Tools Being Used in Restoration Works :- Roller, JCB, Tractor with Trolley	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory	

11/11/24

11/11/24
Signature of Inspector
(Official Seal)