

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E, Motihari	
Name of Block/Road :- Motihari / Motihari Chauradano PWD Road p/multi more To Jindkahiya.	
A. For Road	
1. Damage Location/Chainage :-	
2. Damage Length :- 177.00 M	
3. Nature of Damage (Length Wise)	(i) Breach :- ✓ 177.00 M
	(ii) Crust Damage :- X
	(iii) Only Flank Damage :- X
whether traffic fully/Partialy obstructed :- fully obstructed	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Brick Bats, J	
(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Tractor	
(iii) Restored Length	In open Area :- open area
	In habitation Area :- X
(iv) If Restoration work done in habitation Area give Reason :- X	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory	

J. Kumar

28/11/24
J.E

28/11/24
AE

Signature of Inspector
Executive Engineer
Rural Works Department
Works Division, Chakiya