

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.E (WDW) Sikkhara (Bhale)

Name of Block/Road :- Pachpaken Gurhenwa to Pansu saw Jola

A. For Road

Damage Location/Chainage :-

Damage Length :- 0.075 Km.

Nature of Damage (Length Wise) (i) Breach :-

(ii) Crust Damage :- 0.059 Km.

(iii) Only Flank Damage :-

Whether traffic fully/Partially obstructed :- obstructed

Details of Restoration :-

i) Material Being Used in Restoration :- Brk bak / Ghana metal

ii) Equipment/Tools Being Used in Restoration Works :- JCB / Tractor / Trolley / Roller

iii) Restored Length

In open Area :- 0.059 Km

In habitation Area :-

iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1) Damage Location/Chainage :-

2) No. of Span Damage :-

3) Length of Span :-

4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-

5) Details of Restoration :-

i) Material Being Used in Restoration :-

ii) Equipment/Tools Being Used in Restoration Works :-

iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector
(Official Seal)

30/11/24
EE Bhale

30.11.24
A.E. Raxaul.