

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- <u>Ajay Kumar</u>	
Name of Block/Road :- <u>Amdaheal / 1093-702 Chokh Raghurathpur to Karammulla, Pur</u>	
A. For Road	
1. Damage Location/Chainage :-	
2. Damage Length :- <u>479.100m</u>	
3. Nature of Damage (Length Wise)	(i) Breach :- <u>479.100m</u>
	(ii) Crust Damage :-
	(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed :-	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- <u>Brick balls, Rubble</u>	
(ii) Equipment/Tools Being Used in Restoration Works :- <u>Tractor with Trolley</u>	
(iii) Restored Length <u>479.100m</u>	In open Area :-
	In habitation Area :-
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abutment/ Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- <u>Satisfactory</u>	

Signature of Inspector
(Official Seal)

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
ग्राम प्रमंडल कटिहार