

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-		Pranav Kumar	
Name of Block/Road :-		(Terhagechh) Elhaniphul Sarai Deori School road to Deori	
A. For Road			
1. Damage Location/Chainage :-		20.5 m - CH - 70 m	
2. Damage Length :-		20.5 m	
3. Nature of Damage (Length Wise)		(i) Breach :-	
		(ii) Crust Damage :- Crust Damage	
		(iii) Only Flank Damage :-	
whether traffic fully/Partialiy obstructed :-			
4. Details of Restoration :-			
(i) Material Being Used in Restoration :-		Brick bats	
(ii) Equipment/Tools Being Used in Restoration Works :-			
(iii) Restored Length		In open Area :- 20.5 m.	
		In habitation Area :-	
(iv) If Restoration work done in habitation Area give Reason :-			
B. For Bridge (Size of Bridge/Culvert)			
(1) Damage Location/Chainage :-		N/A	
(2) No. of Span Damage :-			
(3) Length of Span :-			
(4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage) :-			
(5) Details of Restoration :-			
(i) Material Being Used in Restoration :-			
(ii) Equipment/Tools Being Used in Restoration Works :-			
(iii) Restored Length :-			
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-			


 Signature of Inspector
 (Official Seal)