

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.C. Work divn. Kishanganj-1
Name of Block/Road :- Kishanganj / PMUSY Road to KOLHA

A. For Road

1. Damage Location/Chainage :- ch. 185.00 M
2. Damage Length :- 22.50 M
3. Nature of Damage (Length Wise)
 - (i) Breach :- 9.0 M
 - (ii) Crust Damage :- 9.0 M
 - (iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :- Traffic Fully obstructed

4. Details of Restoration :-

- (i) Material Being Used in Restoration :- Brick bats, Earth filling
- (ii) Equipment/Tools Being Used in Restoration Works :- Tractor, JCB Machine
- (iii) Restored Length

In open Area :-	22.50 M
In habitation Area :-	
- (iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

Chd
12/11/24
AE

20/11/24
Signature of Inspector
(Official Seal)