

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-

E. E

Work

divn.

Kishanganj-1

Name of Block/Road :-

Kishanganj/ PHUSY Road to Kacchubari

A. For Road

1. Damage Location/Chainage :-

ch. 450 M, 600 M, 860 M

2. Damage Length :-

16.50 M

3. Nature of Damage (Length Wise)

(i) Breach :-

16.50 M

(ii) Crust Damage :-

16.50 M

(iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :-

Traffic fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :-

Brick bats, Earth Filling

(ii) Equipment/Tools Being Used in Restoration Works :-

Tractor, JCB Machine

(iii) Restored Length

In open Area :-

16.50 M

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

Signature of Inspector
(Official Seal)