

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE R.W.D. works Div. Bardsai	
Name of Block/Road :- Bardsai, Rahmanpur SE Bangalila	
A. For Road	
1. Damage Location/Chainage :-	
2. Damage Length :- 0.354 km	
3. Nature of Damage (Length Wise)	(i) Breach :- 0.354 km
	(ii) Crust Damage :- ✓
	(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed :- fully obstruct	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Bricks & Sand	
(ii) Equipment/Tools Being Used in Restoration Works :- Trolley & JCB	
(iii) Restored Length	In open Area :- ✓
	In habitation Area :-
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-	

Signature of Inspector
(Official Seal)

29/11/2024