

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-

Name of Block/Road :- Elaurav Kumar

(Terhagachh) To 2 Benugachh road se maal to li Benugachh

A. For Road

1. Damage Location/Chainage :- 700m

2. Damage Length :- 11 m

3. Nature of Damage (Length Wise)

(i) Breach :-

(ii) Crust Damage :- crust damage

(iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :-

fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :-

Bricks bats

(ii) Equipment/Tools Being Used in Restoration Works :-

Tractor with Tolly, JCB,

(iii) Restored Length

In open Area :- 11m

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

N/A

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :-

Signature of Inspector
(Official Seal)