

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE, Rural Works Division, Katihar

Name of Block/Road :- Manihari/MMGSY Road to Sirsainadi to/a

A. For Road

1. Damage Location/Chainage :- Lat. 25.35748 Long. 87.681171

2. Damage Length :- 38M + 29M = 67M

3. Nature of Damage (Length Wise) (i) Breach :- 38M + 29M = 67M
(ii) Crust Damage :- -
(iii) Only Flank Damage :- -

whether traffic fully/Partially obstructed :- Fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick bats

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, Loader, JCB, Roller etc

(iii) Restored Length In open Area :- 28M + 29M = 67M
In habitation Area :- -

(iv) If Restoration work done in habitation Area give Reason :- -

B. For Bridge (Size of Bridge/Culvert) NA

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Amesh
25/11/24

Prasen
25/11/24
A.E

25/11/24
Signature of Inspector

(Official Seal)

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमंडल कटिहार