

## Inspection Report For Flood Damage Work

Date:

1 Name of PIUs:

Gopalpur-2

2 Name of Block/Road:

mahusaraya Pith Road to Patharpatti Pul.

A For Road

1 Damage Location / Chainage:

1225m to 1240m

2 Damage Length:

15m

3 Nature of Damage:

Heavy Rain / Flood

4 Details of Restoration Works:

i. Material being used in Restoration Works:

Brick Bats

ii Equipments / Tools being used in Restoration Works:

JCB, Tractor, Trali, Roller etc

iii Procedure taken up in Restoration Works:

Yes

iv Restored Length:

15m

B For Bridge

1 Damage Location / Chainage:

2 Damage Length:

3 Nature of Damage:

4 Details of Restoration Works:

i. Material being used in Restoration Works:

ii Equipments / Tools being used in Restoration Works:

iii Procedure taken up in Restoration Works:

iv Restored Length:

N/A  
work found satisfactory  
13/10/24  
EXECUTIVE ENGINEER  
RURAL WORKS DEPARTMENT  
WORKS DIVISION SIWAN-2  
13/10/24  
AE

JE  
05/10/24

AE  
05-10-24

EE  
05/10-24

S.E