

INSPECTION REPORT FOR MOTORABLE WORK

Name of TTUs :-

EE, Rural Works Division, Kather

Name of Block Road :-

Manikari / Kawaiya to Teldanga

A. For Road

1. Damage Location/Chainage :- Lat: 25.373392 Long: 87.675502

2. Damage Length :- 28.60m

3. Nature of Damage (Length Wise) (i) Breach :- 28.60m

(ii) Crust Damage :-

(iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :- fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick bats

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, JCB, Roller etc

(iii) Restored Length

In open Area :- 28.60m

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert) NA

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Detail of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector

(Official Seal)

कार्यपालक अभियन्ता

। ग्रामीण कार्य विभाग

कार्य प्रमंडल कटिहार

25/11/24
DE