

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- E.C. Barsad.
Name of Block/Road :- R. Gauri/RUPAULI Teekapatti PWD Road to

A. For Road

Dumari Bazar PMGSY

1. Damage Location/Chainage :- 4540, m 4770 m 4940 m.

2. Damage Length :- 0.072 km

3. Nature of Damage (Length Wise)

(i) Breach :-

(ii) Crust Damage :- ☒

(iii) Only Flank Damage :- ☒

whether traffic fully/Partially obstructed :-

4. Details of Restoration :-

(i) Material Being Used in Restoration :- pozzolane betts.

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length

In open Area :- ☒

In habitation Area :- ☐

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :- NA

(2) No. of Span Damage :- NA

(3) Length of Span :- NA

(4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :- NA

(5) Details of Restoration :- NA

(i) Material Being Used in Restoration :- NA

(ii) Equipment/Tools Being Used in Restoration Works :- NA

(iii) Restored Length :- NA

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector
(Official Seal)

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बारसोई, कटिहार