

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- <u>EE RWD, WD(W), Sikharne (Choke)</u>	
Name of Block/Road :- <u>Bhandar Chowk Se Sapahi Nete Hae Jamme ghat tak Path.</u>	
A. For Road	
Damage Location/Chainage :- <u>@ CH-0.2 km</u>	
Damage Length :- <u>0.275 km</u>	
Nature of Damage (Length Wise)	(i) Breach :-
	(ii) Crust Damage :- <u>0.275 km (crust damage)</u>
	(iii) Only Flank Damage :-
Whether traffic fully/Partially obstructed :- <u>Obstructed</u>	
Details of Restoration :-	
Material Being Used in Restoration :- <u>Brick bats / Jamme Khoe</u>	
Equipment/Tools Being Used in Restoration Works :- <u>Roller, Tractor, JCB</u>	
ii) Restored Length	In open Area :-
	In habitation Area :- <u>0.275 km</u>
v) If Restoration work done in habitation Area give Reason :- <u>-</u>	
B. For Bridge (Size of Bridge/Culvert)	
1) Damage Location/Chainage :-	<u>Y</u>
2) No. of Span Damage :-	<u>Y</u>
3) Length of Span :-	<u>Y</u>
4) Nature of Damage (Pier/Abutment/Wing Wall/Approach Road Damage) :-	<u>Y</u>
5) Details of Restoration :-	<u>Y</u>
i) Material Being Used in Restoration :-	<u>Y</u>
ii) Equipment/Tools Being Used in Restoration Works :-	<u>Y</u>
iii) Restored Length :-	<u>Y</u>
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- <u>Satisfactory</u>	

[Signature]
30.11.24.
A.E. Raxaul.

[Signature]
30/11/24
Signature of Inspector
(Official Seal) EE, RWD, Raxaul
EE/Draho