

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
13/ Year maintenance					
House of mace - 100 ft - maintenance					
Recd. from Baridpur to					
Baridpur Kishorewala Jole					
under masonry Sth					
Aug - Dharmidhar chandhuri.					
Andru - 91/SPD / 2000-21.					
Debit Card - 25.3.2022					
Debit Card - 25/3/2023					
① Restoration of premises					
ms allu -					
10 x 15m x .90 x .30 = 40.50 m ³					
2 x 10m x .75 x .30 = 4.50					
45 m ³					
Let me 46.04 m ³					
2. making up of Berms					
shaly ms allu -					
10 x 15m x .90 = 135 m ²					
10 x 15m x .90 = 135					
270 m ²					
Let me 269.16 m ²					
3. masonry of edifice					
ms -					
4. cutting of beam of brick					
10. 2nd					
25/3/23					
① Earth - 85 m ³					
25/3/23					

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of					
1. Restoration of boundaries					
with all boundaries —					
area for survey is				43	
area ①		44.04 m ²			
area 386.14 m ²					17005 =
2. making up of berries					
Shrub with all boundaries —					
area for survey is				43	
area ②		269.16 m ²			
area 5736 m ²					15439 =
3. maintenance of					
area for survey is				43	
area ③		1 m ²			113 =
area 1130.67 ch					
4. cutting of branch of					
10. trees —					
area for survey is				43	
area ④		2 m ²			219 =
area 109.74 ch					33794 =
Add 121.65 T.P. 1/16					4393 =
					38187 =
area 11.36 1/2 bend					4338 =
					33849 =
Continuation					
25/5/2023					
26/3/23					