

MMGSY-SC

Const. of Road from PWD Road to Dhanuk Tola

Schedule XLV-Form No.-134

DIVISION

TABLE

SUB-DIVISION

MEASUREMENT BOOK

Sri Rajiv Ranjan

No. 695

Nike A	Amesv.
15/02/24	15/02/24
OB	OB

44.	Restoration of ruin	
	cups / Berms in soil	
	slits all comp.	
	vide TMS p. 40 - 54	
	9/60 (1/44) 30-99M ³	
	@ 398-45/m ³ —→ 12342w	
$\frac{2}{45}$.	Making up of Berms	
	shoulder with all w/p-	
	vide TMS p. 40 - 54	
	9/61 1/45 - 176 - 40M ³	
	@ 54-16/m ³ —→ 95542w	
$\frac{3}{46}$.	Maintenance of C/D	
	Hume pipe culvert	
	with all w/p-	

21902: w

~~Nikhil~~
~~12/7/29~~

~~Arunav~~
18/07/29
DB.

~~(Wash)~~
~~12/8/29~~