

પ્રમાણિત કરવામાં આવેલ
દેવિ માપી પુત્ર મે માપી
એકલ 100 મુલ દેવિ
મદોપત્ર કાચિયાત R.W.D
પ્રમાણિત કરવામાં આવેલ
પ્રમાણિત કરવામાં આવેલ
પ્રમાણિત કરવામાં આવેલ

Signature
Executive Engineer
RWD Works Division
1998
1.7.21

Sch. XLV - Form No. 134

પ્રમાણિત કરવામાં આવેલ DIVISION

પ્રમાણિત કરવામાં આવેલ SUB-DIVISION
પ્રમાણિત કરવામાં આવેલ

Measurement Book

No.

1222

Name _____

Date of first entry _____

Date of last entry _____

3rd year maintenance

Sch. XLV-Form No.134 13

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- Maintenance of 1st & 2nd Bokoane					
Yachubon 1st to Yachubulige					
Yachubon 1st to Paschim 1st					
77437 sq					
Block - Pakaridagel.					
Agency - 1/2 Daga Construction & Supply.					
Somra, Chakia					
E. Chakia					
Agreement No:- 66 SBO/2/18-19					
Actual Date of Completion:- 31.8.2020					

Maintenance work has been					
done by Agency					
1. Maintenance of Earthen					
Shoulder filling					
2x	5	12.10	0.80		96.80
2x	7	10.05	0.70		98.49
2x	9	8.00	0.60		86.40
2x	11	5.95	0.65		85.08
T					366.77 ²
2. Restoration of Drain					
Cuts with Spd.					
2x	6	8.90	0.75	0.30	24.03
2x	8	7.80	0.65	0.30	24.33

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2 x 10 x 6.70 x 0.70 x 0.30					28.14
2 x 12 x 5.60 x 0.60 x 0.30					24.19
2 x 8 x 4.03 x 0.40 x 0.30					7.73
				T	108.427 ³
8. Main for 1 way rind.					
dy. All up					
4 x 3.70 x 2.60					= 38.48
8 x 1.70 x 0.70					= 9.52
12 x 1.10 x 0.90					= 11.88
10 x 3.50 x 0.25					= 8.75
				T	68.637 ²
4. Repair to both by					
sement. of failed					
7 altered					
4 x 3.70 x 2.60					= 38.48
8 x 1.70 x 0.70					= 9.52
12 x 1.10 x 0.90					= 11.88
10 x 3.50 x 0.25					= 8.75
				T	68.637 ²
5. Patch repair on side					
2.16 - 1 foot hole					
4 x 3.70 x 2.60					38.48
8 x 1.70 x 0.70					9.52
12 x 1.10 x 0.90					11.88
10 x 3.50 x 0.25					8.75
				T	68.637 ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
6. Gaining H.P. culvert					
by 1. way					2 No
7. Cutting & branches from					
by 1. way					10 No
8. Cutting & stumps from					
d. way					20.01 No
9. Turning from and					
roads					
2 x 27 x 30.0 x 0.50					= 810.0
					T 810.0 m ²
10. White washing of					
bars wall					774.49 m ²
Top.	4	6.150	0.40		= 9.84
End.	8	0.40	0.60		= 1.92
S. f.	4	6.150	0.60		= 14.76
					T 26.52 m ²
11. Plv and app. 2000 ft.					
within bend cement path					
2 x 25 x 25.0 x 0.10					= 125.00
					T 125.00 m ²
12. Plv and laying of hot					
app. Thermoplastic comp.					
2.5 mm thick R. Marking					
2 x 53 x 30.0 x 0.10					= 318.0
2 x 1 x 21.0 x 0.10					= 2.20
					T 320.20 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		P. 14			
68.63 y^2 @ 9.		271.94		6.	18663.~
6/7		72.1			9 H.P. culverts
		by 2. way			
		P. 15			
240 @ 9.		1131.64		1.	2263.~
7/12		cutting 9. trenches of			
		tree			
		P. 15			
1040 @ 4		107.48		6.	1075.~
8/13		cutting 9. shrubs from			
		1. way			
		P. 15			
20.01 No		6.60		1.	132.~
9/14		Trimming 9. grass			
		weeds from 1. way.			
		P. 15			
774.497 ² @ 9.		2.20		9.	1704.~
10/15		White washing 9. para.			
		bet wall			
		P. 15			
26.527 ² @ 9.		16.80		9.	446.~
11/10		P.V. and slab 20. d.			
		water band c. post			
		P. 15			
125.07 ² @ 9.		104.91		4.	13114.2

Continuation

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
12/10 (M) P. 12					
abb. 1000					
		8.15			
320.20 7 ² @ 8.		867.77		9.	277860 ~
12/11					
12/11					
		8.16			
0.288 km (Q) R.		749.0		9.	216 ~
14/9					
		8.16			
4.200 km (Q) R.		1087.63		6.	4568 ~

R. 425684 ~

less 0.05 ~ below ~

213 = 0

R. - 425471 = 0

24.10.23
J.E.

2.1.24
A.E.

of actual measurement

Soss - 63.148 43

Chipm - 1.853 73

Seed - 0.411 73

Emul - 0.034 717

Bite - 0.274 119

24.10.23
J.E.

Continuation