

Shivmendis Davidnegar Check (Hajipur-Mahmud)

Schedule XLV-Form No. 134

Path) Se South Barga Ghat

M.M.G.S.Y
(SC)

Mahmud

DIVISION

Bidpur

SUB-DIVISION

MEASUREMENT BOOK

760

2nd year Maintenances Bill

Sch. XLV—Form No. 134

41

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- Shiv Mandir sanddargah					
Chowk (Hajipur Mahanir Park)					
Se South Ganga Ghate					
Agency:- life vision const Pvt Ltd					
Ag no:- 89/mm/2020-21					
Date of work order:- 07-01-2021					
Date of Actual completion:- 05-01-2022					
3.5 cm - 11					312
5.11					901
1. P21					905
① Restoration of Rain cuts /					
Terms with soil d- water					

$$\begin{aligned}
 5 \times 30.10 \times 0.85 \times 0.30 &= 38.25 \text{ m}^3 \\
 5 \times 30.10 \times 0.85 \times 0.30 &= 38.25 \text{ m}^3 \\
 3 \times 30.10 \times 0.87 \times 0.30 &= 23.49 \text{ m}^3 \\
 \text{Total} &= 99.99 \text{ m}^3
 \end{aligned}$$

- ② Maintenance of Road sign - 0.20 km
- ③ Maintenance of 200 m and km sign — 0.25 km

Signature
5/3/24
J.C.

Signature
5/3/24
AR

Abstract of cost

42

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Conter are
	No.	L.	B.	D.	
1) Restoration of Raincoys/Bumy					
With soil do-to all complete job.					
Qty vide item no - 1					
P.No - 41 T.M. B = 99.99 m ³					
419.31/m ³ ————— RS 41927 =					
2) maintenance of Road signs					
do-do all complete job.					
Qty vide item no - 2					
P.No - 41 T.M. B = 0.20 Km					
1145.81/Km ————— RS 227 = 0					
3) maintenance of 2.10 m and					
6m grous do-to all complete job.					
Qty vide item no - 3					
P.No - 41 T.M. B = 0.25 Km					
654.66/Km ————— RS 162 = 0					
Total					RS 42316 = 0
Gst 12%					RS 5078 = 0
Loc 1%					RS 423 = 0
Total					RS 47817 = 0
Below 13.55%					RS 6479 = 0
Total					RS 41338 = 0
By					
5/3/24					5/3/24
J.R.					AE