

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4th year Maintenance					
Name of work: - Maint.					
of road from Dhanawa					
to Harpandigha Under					
MMGLY NDB BRICS					
Agency - Kumar Construction,					
Station road, Hilsa					
Agreement no - 35831/2018-2019					
Actual Date of completion -					
19/06/2020					
Date of entry					
28/06/2020					

① Restoration of sarbuit
with soil.

$$2 \times 3 \times 30.0m \times 0.50m \times 0.30m = 27.0m^3$$

$$2 \times 5 \times 30.0m \times 0.60m \times 0.30m = 54.0m^3$$

$$2 \times 6 \times 30.0m \times 0.80m \times 0.30m = 86.40m^3$$

$$2 \times 26.0m \times 0.95 \times 0.30m = 14.82m^3$$

$$182.22m^3$$

② Maintenance of berm/
shoulder

$$2 \times 10 \times 30.0m \times 0.85 = 510.0m^3$$

$$2 \times 10 \times 30.0m \times 0.80m = 480.0m^3$$

$$2 \times 6.0m \times 1.0m = 12.0m^3$$

$$1002.0m^3$$

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			BF		2,84,929=
⑦ Maint. of 200 m & km stone					
0.360 km vide TMS Pg					
⑧ 647=48					233=00
					2,85,162=
0.03% below as per Agreement (-)					86=00
					2,85,076=
28/06/2024 AE					
Material statement-					
① Soil - 330.0m ³					
② stonechips - 13.50m ³					
③ Stonemetal - 9.40m ³					
④ Screening - 1.90m ³					
⑤ Bitumen - 1.122m ³					
28/06/2024 AE					

Continuation