

5th year maintenance

42

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W-	Samalpur Path to				
	Gudga Jela Juk				
Agency-	Ram Babu Singh				
	Basauli Muzaffarpur				
Agreement No-	156/SB.D/2018-19				
Date of work order-	05/03/2019				
Date of completion-	08/12/2019				
Actual date of completion-	20/09/2020				

Measurement

①

Restoration of Road

Cuts

F/I

$$8 \times 16.00m \times 0.85m \times 0.30m = 32.64m^3$$

$$8 \times 11.00m \times 0.90m \times 0.30m = 23.76m^3$$

$$4 \times 6.00m \times 0.75m \times 0.30m = 5.40m^3$$

$$\text{Total RS} = 61.80m^3$$

②

Maintⁿ of Furthen

Shoulder

F/I

$$2 \times 4 \times 16.00m \times 0.85m = 112.64m^2$$

$$2 \times 9 \times 17.00m \times 0.75m = 229.5m^2$$

$$\text{Total Qty} = 342.14m^2$$

③

Repair to Pot holes mix

Seal Surfacing - - F/I

$$7 \times 2.00m \times 1.56m = 21.84m^2$$

$$4 \times 8.10m \times 2.25m = 27.90m^2$$

$$5 \times 2.95m \times 2.00m = 29.5m^2$$

$$\text{Continuation Total Qty} = 79.24m^2$$

Continuation