

5th year maintenance

11

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
1. Name of work: Hari Kishor Chaudhary re. Ghar to mohha madhwar kanti Talu					
2. Name of Agency: M/S Jadedamth Singh					
3. Agreement No: 92/SB/2018-19					
4. Actual dt. of completion: 01.08.2019					
— measurement as below —					
① Restoration of drains with soil sloped					
	5	30.0	0.90	0.30	= 40.50
	6	30.0	1.0	0.30	= 54.0
	7	30.0	0.75	0.28	= 44.10
	2	30.0	0.60	0.28	= 10.08
	1	20.50	0.65	0.30	= 3.997
	1	30.0	0.70	0.30	= 6.30
	2	20.60	0.60	0.28	= 6.921
	3	30.0	0.60	0.28	= 15.12
	3	25.20	0.60	0.28	= 12.70
	1	1.50	0.40	0.30	= 0.18
	1	1.80	0.42	0.30	= 0.230
	1	1.90	0.45	0.30	= 0.257
	1	2.0	0.50	0.30	= 0.30
	1	1.50	0.40	0.30	= 0.18
					Qty = 194.765 m ³
					Say Qty = 194.64 m ³
② maintenance of earthen					

Continuation

P.T.O.

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
			BPB	181760	=W
① patch repair on already					
4 filled potholes in					
Qty = 250.31 m ² side					
			TMBP - (15)		
② 262 = 60/m ² - B				65731	=W
⑤ maintenance of					
5 pipe current work					
Qty = 2.0 m ² side					
			page (15)		
③ 1131 = 68/each B				9053	=W
⑥ maintenance of					
15" slab type culvert					
— on E					

Qty = 7.0 m ² side					
			TMBP - (15)		
④ 2336 = 82/each B				9347	=W
⑦ maintenance of					
15" 200 m & 100 m					
— on E					
Qty = 2.59 km ²					
			TMBP - (15)		
⑧ 728 = 56/km - B				1887	=W
⑧ providing and laying					
5 of hot applied thermo-					
plastic compound 2.5 mm					
thick — on E					
Qty = 51840					
Continuation page ①					
⑨ 770 = 48/m ² - B				399417	=W
				667195	=W

01.08.2024
J-E

Scanned with CamScanner