

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1st year maintenance				
N/w. TO 4 to Kathitola (Katabmiga Tola)					
Agency - Manoj Prasad					
Agreement No - 31/5.B.2/22-23					
Date of work order - 5/1/23					
Date of completion Actual - 30/9/23					
Date of Entry - 1/10/24					
(1) Restoration of farm cut					
with sand 200 - 6/1					
	2	9.2	1.2	1.50	9.7 m ²
	4	19.2	1.80	1.50	20.52 m ²
	2	4.2	1.20	1.20	1.6 m ²
					<u>29.82 m²</u>
(2) making up Berms					
shoulder, stripping					
excess soil.					
	6	12	1.50		180 m ²
	3	10	1.50		45 m ²
	5	24	1.70		204 m ²
					<u>429 m²</u>
(2) pre-mix carpet with					
seal coat type B					
	8	.60	.50		2.4 m ²
	15	.75	.50		5.6 m ²
	12	.60	.60		4.3 m ²
	24	.75	.30		5.4 m ²
					17.7 m ²
				Limit	17.58 m ²

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of work					
(1) Restoration of rain cut with soil					
34.82 m ³ (estimate T.M.B P 37)					
at 407.70/m ³					10119 =
(2) making up Berms shoulder stripping excess soil					
429 m ² (estimate T.M.B P 37)					
at 60.79/m ²					26079 =
(3) Premix carpet with Seal coat tube B.					
17.58 m ² (estimate T.M.B P 37)					
(4) Maint of C2 work (H.P culvert)					
1 Nos (estimate T.M.B P 38)					
at 1182.79/1 Nos					1183 =
(5) Maint of C2 work (Slab culvert)					
1 Nos (estimate T.M.B P 38)					
at 2426.45/1 Nos					2426 =
(6) Maint of road sign					
177 km (estimate T.M.B P 38)					
at 1117.64/km					860 =
(7) Maint of ground kerbstone					
123 km (estimate T.M.B P 38)					
at 733.93/km					169 =
(8) Cutting of Branches of trees					
2 Nos (estimate T.M.B P 38)					
at 115.92/1 Nos					232 =

Continuation

Scanned with OKEN Scanner