

Mmgsy (Gien) - Loss to Sacrificence.

Ag No. 19 SED | 19-20
Shedule XLV Form No. 134.

Raddus alive. Shergahat DIVISION

Shergahat SUB-DIVISION
Agency :- Vande mand shanti Const.
0.11%

Measurement Book

1083.

Ag Value - 63.04900 Cateh.

28.8.19

to
19.05.20

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd year maintenance bill					
N/W - Maintenance of road from					
1055 to Safichak.					
Under Shergarhi Block.					
Agency - Mrs. Mani Shandi (Sister)					
55 Ram Bigha Guna.					
Dist - Gaya.					
Agreement - 19 SBT/2019-20					
date of Agreement - 20.8.2019					
date of comp - 19.8.2020					
Actual date of comp -					
betas 0.11%					
date of memo					

1	Restoration of main			
15.1 A	Cut & fill			
	2x 20x 0.90x 0.30 = 10.80m ³			
	2x 20x 0.80x 0.30 = 10.80m ³			
	2x 30x 0.80x 0.30 = 14.4m ³			
	1x 6.60x 1.17x 0.30 = 1.98m ³			
				T = 37.98m ³

2	Making up of Berms/			
15.2	Shoulder drains			
	2x 25x 0.80 = 40m ²			
	2x 30m x 0.70 = 42m ²			
	2x 25m x 0.70 = 35m ²			
	2x 30x 0.80 = 48m ²			
	2x 29x 0.80 = 46.4m ²			
				T = 211.4m ²
				Rest 210.94m ²

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3) 15.5.11	patch repair over pot holes bituminous surface with 20mm thickness - M.S. do.				
(4) 15.5.11	2x	20	x 0.80	= 32 m ²	
	2x	9	x 0.90	= 16.2 m ²	
	2x	8	x 0.80	= 12.8 m ²	
	2x	0.50	x 0.50	= 0.50 m ²	
				T- 29.5 Less 29.30 m ²	
(4) 15.5.11	Maintenance of D Hp culvert chain 0.2 nos -				
(5) 15.5.11	Maintenance of road signals do. 0.12 km				
(6) 15.5.11	Maintenance of 200m 2 km gate chain 0.150 km -				
(7) 15.12.11	Cutting of Branches of tree chain - 6 Nos -				
(8) 15.12.11	Cutting of branches of shrubs from Roadway - do 625 Nos -				

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(10/12/11)	Turning of grass				
	and weeds etc.				
	2x	30x	0.90	=	54 m ²
	2x	25x	0.80	=	40 m ²
	2x	30x	1.00	=	60 m²
	2x	30x	0.70	=	45 m ²
	2x	25x	0.90	=	45 m ²
	3x	30mx	0.80	=	72 m ²
	1x	1.00x	1.00	=	1 m ²
				T=	317 m ²
(10/12/13)	White washing of parapet				
	of 6 walls etc.				

Side	2x	6.50	x	0.60	=	7.80
Top	2x	6.50	x	0.40	=	4.92 m ²
front	2x	6.50	x	0.40	=	4.92 m ²
						17.22 m ²
	Sum	2 nless	x	17.22 m ²	=	34.44 m ²

(10/12/13)
17.8.52

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(15.1) Abstract of 10th.					
Restoration of rain cut channels.					
Qty vide Tmp. 47					
Item no. 1					
37.98 m ³ @ 380.58/m ³ Rs = 14457=					
(15.2) Making up of borrow shoulder ditches					
Qty vide Tmp. 47					
Item no. 2					
210.94 m ² @ 58 37/m ² Rs = 12313=					
(15.3) Patch repair over Bituminous surface					
Qty vide Tmp. 48					
Item no. 3					
29.3 m ² @ 270.30/m ² Rs = 7920=					
(15.4) Maintenance of CD					
Hp culvert ditches					
02 alos @ 1117.00/each = 2234=					
(15.5) Maintenance of road					
Bituminous ditches					
Qty vide Tmp. 48					
Item no. 5					
0.120 km @ 81074.51/km = 12920					
(15.11) Marking of 200m & 400m					
Qty vide Tmp. 48 Item 6					
0.150 km @ 657.71/km = 9920					

Continuation

T = 32146=

Sch. XLV-Form No. 134

51

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
7 15.12.1				BF RS =	321462
				Cutting of branches of tree also	
				Qty like parts p. 48	
				Items 7	
6 Nos @ 106.52/6 each Rs.					6295
8 15.12.11				Cutting of shrubs from Roadway also	
				Qty like TMBH 48	
				Items 8	
625 Nos @ 6.54 Each =					408820
9 15.12.11				Turning of gours	
				Qty like TMBH 49	
				Items 9	
137 m ² @ 2.12/m ² Rs =					691200
10 15.12				White Washing of CD	
				Qty like TMBH 49	
				Items 10	
34.44 m ² @ 16.46/m ² Rs =					567200
				Total Rs =	431212
less below 0.11%				Rs =	472
				Total Rs =	430740
W/te 15.12.2024					

Continuation