

5th year maintenance

95

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Maint. of Road from To to
Machhous Digha

Agency - Curid Infrastructure Pvt. Ltd.

Ag. No - 52 SOD/2014-15

Actual D. No. - 28.03.2019

① Restoration of Rain cuts -

L.H.S - 25 x 5.00 x 1.90 x 0.35 = 83.12

R.H.S - 20 x 4.50 x 1.75 x 0.30 = 47.25

L.H.S - 18 x 3.50 x 1.95 x 0.300 = 36.85

R.H.S - 28 x 2.90 x 1.10 x 0.35 = 31.26

L.H.S - 30 x 2.00 x 1.15 x 0.35 = 24.15

R.H.S - 35 x 3.70 x 1.20 x 0.35 = 54.39

L.H.S - 27 x 2.90 x 1.30 x 0.30 = 30.53

32 x 2.50 x 1.20 x 0.35 = 33.60

R.H.S - 27 x 3.10 x 1.15 x 0.30 = 27.94

369.09 m³

② Maintenance of Earthen

Shoulder

L.H.S { 10 x 20.00 x 0.90 = 180.00

15 x 15.00 x 0.85 = 191.25

R.H.S { 20 x 20.00 x 0.90 = 360.00

25 x 15.00 x 0.95 = 337.50

L.H.S { 20 x 10.00 x 0.90 = 180.00

30 x 12.00 x 0.85 = 306.00

R.H.S - 15 x 25.00 x 0.90 = 337.50

L.H.S - 12 x 10.00 x 0.90 = 108.00

2000.00

2000.00 m²

R.H.S - 10 x 10.00 x 8.00 = 80.00

Continuation

2080.00 m²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Rly side THE R-96					
3380.w @ R. 1.55/m ² - R. 5208 =					
					R. 38642.6 =
					R. 38642.6 =
Less 10% Below → G)					R. 38643 =
					R. 347783 =
04/04/29 JS					
Motives:					
G/w - 681.127 m ³					
S/chspc - 8.921 m ³					
s/malel - 15.035 m ³					
(S90) - 0.789 MT					
4/04/29 JS					