

1st Year Maintenance

1

Name of Work-

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work = Maint. of Road from					
Prasay to Kumbhar Pali					
Agency = Parmar Enterprises					
Ag. No. = 150820/Margy/2021-2022					
Actual comp. = 11.09.2023					
Actual completion - 11/09/2022 11/09/23					

Record Entry

Restoration of Rainals

	Do				
12x	4.40	x 1.00	x 0.30	=	15.84
16x	4.60	x 1.05	x 0.30	=	20.59
9x	4.90	x 0.95	x 0.30	=	12.57
8x	4.90	x 0.95	x 0.30	=	11.17
7x	5.30	x 0.90	x 0.30	=	10.02
6x	6.40	x 0.85	x 0.30	=	9.79
8x	5.30	x 0.80	x 0.30	=	10.18
9x	5.10	x 1.125	x 0.30	=	15.49
4x	5.50	x 0.85	x 0.30	=	5.61
					111.26 m ³

Continuation

Material used :-	
Earthwork	389.066 m ³
Emulsion	16.00 kg
Bitumen	111.00 kg
Stone chips	1.59 m ³
Sand	0.309 m ³

Continuation