

1st Year Maintenance

Name of Work-

1

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road					
from NH-28 Madhukon to Yadav					
Tola Chakbare under MWSY					
Agency- M/S. Devendra Kumar &					
Company					
At- Kadarhatta, P.O- Barji,					
P.S- Motipur, Dist- Muzaffarpur					
Agreement No- 07 SBD/2121-22					
Date of start- 31/07/2021					
Date of completion- 30/07/2022					
Actual date of completion- 30-7-2022					
① Restoration of Rain cuts					
1 X	7.10	X 1.20	X 0.25 =	2.13 m ²	
1 X	6.20	X 1.15	X 0.25 =	1.78 m ²	
2 X	8.00	X 1.20	X 0.30 =	5.76 m ²	
1 X	6.50	X 1.10	X 0.30 =	2.11 m ²	
2 X	9.00	X 1.25	X 0.25 =	5.62 m ²	
1 X	8.50	X 1.25	X 0.30 =	3.19 m ²	
1 X	7.50	X 1.15	X 0.30 =	2.59 m ²	
4 X	8.00	X 1.25	X 0.30 =	12.00 m ²	
2 X	10.75	X 1.20	X 0.30 =	7.74 m ²	
3 X	11.50	X 1.25	X 0.25 =	10.78 m ²	
1 X	9.00	X 1.28	X 0.25 =	2.88 m ²	
Continuation					56.61 m ²

Abstract of cost

Sch. XLV-Form No.134

5

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of kaim cut					
Q-VINBP 1(1) =			56.61m		
P 4(8) =			37.10m		
			93.71m		
e R. - 404 = 06/11					R. - 37864 = 0
② Main long run of earthen					
shoulder					
Q-VINBP 2(2) =			315.86m		
P 3(6) =			204.98m		
			520.84m		
e R. - 60 = 28/11					R. 31378 = 0
③ Maintenance of bituminous					
surface road					
Q-VINBP 3(3) =			43.36m		
e R. - 253.55/11					R. 10994 = 0
④ Maintenance of H.B culvert					
Q-VINBP 2(3) =			2 Nm		
e R. - 1166 = 58 per km					R. 2333 = 0
⑤ Maintenance of slab					
culvert					
Q-VINBP 2(4) =			2 Nm		
e R. - 2794.96/culvert					R. 4790 = 0
⑥ Maintenance of earthen stone					
Q-VINBP 2(5) =			2.1201 km		
e R. - 748 = 22/km					R. 1586 = 0

Continuation

88945 = 0

