

Sch. XLV Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Reconstr. work					
Debris				10/6/2024	
1. Boundary and appurtenances					
7. Primer and walls all complete					
Area as per survey					
As 10mm 5mm 1mm patch work					
Value per sq. m. @ 98/-					
1				1051.37 m ²	
2. Boundary and appurtenances					
7. Primer and walls all complete					
Area as per survey					
Primer and walls				1051.37 m ²	
C.C. Portico patch work					
7 x 3 m x 2 m				= 54 m ²	
4 x 5 m + 3.75				= 75 m ²	
6 x 4 m + 1.50				= 24 m ²	
				1204.37 m ²	
3. Boundary and appurtenances					
8. Cement concrete primer and appurtenances					
Area as per survey					
Value per sq. m. @ 2					
				1204.37 m ²	
Unit				1204.37 m ²	
				10/6/24	
				5	

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
b. beam	circum				
		4 m			
c. beam & support beam		4 m			
d. beam		2 m			
Y 27/30	Providing and laying				
	of hot applied thin floor				
	Compound - using all components				
© BT Portion					
	34 m x 3 m x 2 x .100				204.00
	1 x 2 m x 2 x .100				4.00
	2 x 3 m x 2 x .100				12.00
	1 x 15 m x 2 x .100				3.00
					223.00
b. pedestrian crossing					
	all components				
	3 x 6 m x .5 x 2				18.00
c. c-c Portion					
	6 x 3 m x 2 x .100				36.00
	1 x 2 m x 2 x .100				4.00
					40.00
8/15	AP				Sum
	10/12/24				18/07/24
					AL
	work has been completed as per				
	specification and direction of E.I.				
	AP				Sum
	10/12/24				18/07/24
					AL

Continuation