

3rd year maint

8

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N.W. - NH 106 to terasi village yeraji					
bhalumahi gaudhiyaji road					
Agency - M/S Anirudh Saksmani					
Agg No. - 06 SBD/2019-20					
D.O. start - 7. 3. 2019					
A.D. O. com - 09. 08. 21					
	10	3.00	1.5	0.3	13.50 m ³
(11) Restoration of Ram					
cutt. do					
	10	3.00	1.5	0.3	13.50 m ³
	25	2.5	1.3	0.3	24.38 m ³
	18	1.40	1.50	0.30	8.10 m ³
	15	4.20	1.10	0.30	20.79 m ³
	10	2.00	1.10	0.40	8.80 m ³
	15	2.10	1.40	0.35	15.44 m ³
	20	2.80	1.50	0.40	33.60 m ³
	37	3.00	1.70	0.30	56.61 m ³
	10	4.00	1.60	0.35	22.40 m ³
	25	2.00	1.60	0.40	32.00 m ³
	15	2.10	0.60	0.30	5.67 m ³
	22	2.5	1.20	0.30	19.80 m ³
	21	2.25	0.60	0.35	26.46 m ³
	30	1.00	0.9		287.63 m ³
(212) Maint of gutter					558 m ³
Shoulder do					568 m ³
	30	3.00	0.80		72 m ²
	35	4.00	0.90		126 m ²
					198 m ²

Continuation

40

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Box culvert					
	2x2	12x	0.40	=	19.20m ²
(2-13)	2x4	12x	0.60	=	57.60m ²
10	2x	4.00x	0.40x	0.60	1.92m ²
(11)	5x	2x6.15x	0.40	=	24.60m ²
	5x	4x8.15x	0.60	=	73.80m ²
	5x	4x0.60x	0.40	=	4.80m ²
(8/12/11)					181.92m ²
<i>(Signature)</i> 28/9/24 S.E. <i>(Signature)</i> 28/9/24 M. L.					
(8/12/11)					NE
(5/12/11)					

Box culvert	5x2	30x	0.40	=	
	2x4	12x	0.60	=	
	2x	4.00x	0.40x	0.60	
(2/3/12)	5x	2x6.15x	0.40	=	
08	2x	4.00x	0.40x	0.60	80.80m ²
09	1x2	12x	0.60	=	
	2x	4.00x	0.40x	0.60	
(5/12)	5x	2x6.15x	0.40	=	
08	2x	4.00x	0.40x	0.60	10/80.80m ²
09	1x2	12x	0.60	=	
	2x	4.00x	0.40x	0.60	

Continuation