

PANMUSY

Schedule XLV Form No. 134.

^{PANMUSY}
^{PANMUSY} Road Rumbhodus HACHUNMI Sioda to Hiasarpur
Shivnarayan Mandak ke ghar Tak.

DIVISION

Chhatpur

SUB-DIVISION

Measurement Book

M.B. NO-909

Ma Construction

Date of Measurement-
No. and date of agreement
(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:-					
MMASy					
Hasanpur					
Ke Ghor tak					
M/cont					
Mga construction					
Agg No					
-48/SBD/MMASy/2021-21					
Date of work					
29-07-2021					
Date completion					
28.07.2022					
Date of measurement					

① Measurement Entry

Pro. Setting out w. D.M. ds
and refer pillar

All job completed

Qty - 18 m²

② Pro. clearing & Grubbing of Road of load ds

All job completed

10 x 100m x 3.5m = 3500

10 x 100m x 3.5m = 3500

1 x 100m x 3.5m = 350

2 x 100m x 3.5m = 700

Total Qty = 8050 m²

1st years maintenance

49

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - M.M. 1st year					
completing the CRUP Sina					
to hasanpur shinnapayan					
mandal ke 5037					
Name of Agency - MRA construction					
date of Intre :- 02/04/24					
(1.) maintenance of rain canal					
$13 \times 30 \times 1.0 \times 0.300 = 117$					
Unit Qty - 116.94 m ³					
CRS. 404.6 $\rightarrow$ 47048					
(2.) maintenance of solder..					
do-do all complete job					
$20 \times 30 \text{ m} \times 1.0 \text{ m} = 600$					
CRS. 60.28 $\rightarrow$ 36168					
(3.) Repair of pot holes filled					
with 75 mm BMX 1.25 do-do					
all complete job.					
(3.) maintenance of c/p works					
(home pipe culvert) do-do					
complete					
2 No CR. 116.5 $\rightarrow$ 2333					
(4.) maintenance of c/p works					
(slab culvert)					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D.	
BH RS → RS 91936					
less 10.79 RS - 199195852					
RS → 82017					
Sum					
2918124					
AE					