

Name of Road :- Kari Mondal House To

PMUGSY Road Loc 42

Schedule XLY-Form No. 134

PMUGSY-SC

Tivernigant

DIVISION

Black-ribon.

SUB-DIVISION

M.B. No- 814

MEASUREMENT BOOK

Mga Construction

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2 years maintenance					
N/work - Kalamandal House to Pithury L042					
Agency Name - Maa Corporation					
Date of entry - 10/10/2023					
① Restoration of gained					
2 X 79m X 1 X 0.3m					
= 97.9m ³ CR 904.06 =					19146.00
② Shoulder surface to achieve					
2 X 5 X 30m X 1m = 360m ²					
Limit 357.55 CR 60.28 =					21565.40
③ With mix seal surfacing					
3 X 1.3m X 2m = 7.8m ²					
9 X 1.6m X 2m = 28.8					
Total 36.6m ²					
Limit 36.01 CR 250.73 =					9168.40
④ maintenance of C/D work					
2 No CR 1166.58 →					2333.40
Total →					52212
W.S.T - 13.1 →					6787
S. Fee →					28
Total -					59027

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Less below 19%				$\rightarrow$	<u>112</u>
Total				$\rightarrow$	<u>58915.00</u>
③. Maint. of Road sign.					
0.13 km @ 1104.58 Rs					$= 144.60$
Total					$= 52353.00$
L.C + G.S.T.					$= 6805.89$
(13%)					
S. fee					$= 28.20$
Total					$= 59,186.00$
Less below 19%					$= 119.45$
Total					$= 59073.55$
/					

12 km
10/10/22
02