

4th years maintenance

70

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Name of work: Hilsa-fathha					
Road to posanda mmensy (BRICS)					
2) Name of Agency: M/S Global solutions					
3) Agreement no: SBD/5/2018-19					
4) Actual date of completion: 21-07-2020					
① Restoration of rain culvert					
2 x 30.00 x 1.10 x 0.30 =					19.80m ³
5 x 30.00 x 0.95 x 0.30 =					42.75m ³
6 x 30.00 x 0.75 x 0.30 =					40.50m ³
7 x 30.00 x 1.12 x 0.30 =					70.56m ³
6 x 30.00 x 0.85 x 0.30 =					45.90m ³
4 x 30.00 x 0.90 x 0.30 =					32.40m ³
8 x 30.00 x 0.70 x 0.30 =					50.40m ³
4 x 30.00 x 0.92 x 0.30 =					33.12m³
total =					335.43m ³
② making up of Berms/ Shoulder stripping					
2 x 7 x 30.00 x 0.50 =					210.00m ²
2 x 8 x 30.00 x 0.48 =					230.40m ²
2 x 4 x 30.00 x 0.44 =					105.60m ²
2 x 9 x 30.00 x 0.49 =					264.60m ²
2 x 8 x 30.00 x 0.47 =					225.60m ²
2 x 7 x 30.00 x 0.45 =					189.00m ²
2 x 6 x 30.00 x 0.46 =					165.60m ²
total =					1390.80m ²
③ patch repair filled with 75mm WBM					
0.1 x 15.70 x 3.75 =					59.06m ²

Continuation

[illegible]