

2nd year maintenance

42

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work? Bargave Phala to Ajitpur Harpur					
2. Name of Agency? Mandikshora Thakur					
3. Agreement No. 12/BSD/2020-21					
4. Actual dt. of completion; 18/10/2022					
<u>Measurement as below—</u>					
(I) Restoration Barinuts with soil level					
1x 30.0 x 0.70 x 0.30 = 6.30					
1x 20.50 x 0.65 x 0.32 = 4.264					
1x 20.60 x 0.72 x 0.28 = 4.152					
1x 30.0 x 0.70 x 0.30 = 6.30					
1x 30.0 x 0.68 x 0.30 = 6.120					
5x 30.0 x 0.70 x 0.30 = 31.50					
5x 30.0 x 0.70 x 0.30 = 31.50					
1x 30.0 x 0.70 x 0.30 = 6.30					
1x 35.0 x 0.60 x 0.30 = 6.30					
1x 20 x 0.60 x 0.28 = 3.36					
				Qty = 100.336 _{m³}	
				Say Qty = 99.33 m³	
(II) maintenance of earthen shoulder wall					
2x 30.0 x 0.70 = 42.0					
3x 30.0 x 0.68 = 61.20					
4x 30.0 x 0.65 = 78.0					
3x 30.0 x 0.52 = 46.80					
				C.O. Qty = 228.0 m³	

Continuation

१७०

Continuation