

4th year Maint. bill

31

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/A - Maint. of road from Lo21 to Harizen tola under GTSNY					
H/A - Ravi Kumar					
Raja Bazar Mohihari					
A99. No - 68 SED/2018-19					
Actual date of comp.					
				04-09-2019	
4 th year Maint. Period					
05-09-2022 to 04-09-2025					

① Restoration of road cut etc.					
	2x	6.0x	1.20x	0.25 =	3.60m ³
	1x	7.10x	1.25x	0.25 =	2.22m ³
	2x	8.0x	1.20x	0.30 =	5.76m ³
	10x	6.50x	1.10x	0.30 =	21.45m ³
	5x	5.00x	0.90x	0.25 =	5.625m ³
	4x	7.00x	1.15x	0.30 =	9.66m ³
	1x	12.0x	1.10x	0.30 =	3.96m ³
	1x	2.50x	1.00x	0.25 =	0.625m ³
					= 52.90m ³

(3) Work done at ...

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract</u>					
① Restoration of rain cuts etc.					
Qty vide T.M.B.P. No. (31)					
$= 52.90 M^3$ @ $365 = 25/M^3$					
					$R 19322/-$
② Maint. of earthen shoulder etc.					
Qty vide T.M.B.P. No. (32)					
$= 293.225 M^3$ @ $354 = 37/M^3$					
					$R 15948/-$
③ Maint. of boundary					
K.M. Stone etc.					
Qty vide T.M.B.P. No. (32)					
$= 0.700 KM$ @ $740 = 27/KM$					
					$R 518/-$
					$R 35,783/-$
Less 0.07% below					
as per Agg.					$R 25/-$
					$R 35,758/-$
<u>Shady</u> <u>land</u>					
05.09.23					
2. E					
					AE
<u>Material Statement</u>					
① E/W = $52.90 M^3$					
<u>Shady</u>					
05.09.23					
2. C					
Continuation					