

2nd year maintenance

Sch. XLV-Form No. 134

22

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

N/w: Maintenance of road from
Muktapur guanti to 1043 tak
under MHCISY (NDB BRISG).

Agency - M/S Rem Sagar Rai & Co.

Ag. No - 51 (SBD) / 2021-22

Dated actual Completion - 26.10.2022

① Restoration of earthen cut -

$$12 \times 3.75 \times 0.95 \times 0.30 = 10.12$$

$$9 \times 4.10 \times 0.90 \times 0.35 = 11.62$$

$$10 \times 2.75 \times 0.85 \times 0.20 = 7.4$$

$$11 \times 3.50 \times 0.70 \times 0.35 = 9.43$$

$$\underline{\underline{38.18 \text{ m}^3}}$$

② Maintenance of earthen shoulder -

$$10 \times 3.50 \times 0.70 = 24.50$$

$$18 \times 4.00 \times 0.80 = 57.60$$

$$16 \times 5.00 \times 0.75 = 60.00$$

$$12 \times 6.00 \times 0.85 = 61.20$$

$$\underline{\underline{203.30 \text{ m}^2}}$$

③ Maintenance of Road sign -

0.615 km

④ Tarmoring of gravel -

$$2 \times 20 \times 30.00 \times 0.45 = 540.00 \text{ m}^2$$

[Signature]
05/10/24
OFF

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Abstract of coll.

① Restoration of Boundary -

Qty wide THB R (22)

38.18 m³ @ R 386.03/m³ — R 14739.0

② Maint. of earthen shoulder -

Qty wide THB R (22)

203.30 m² @ R 57.54/m² — R 11698

③ Maint. of Road Sign -

Qty wide THB R (22)

0.615 km @ R 1077.81/km — R 663.0

④ Trimming of grass -

Qty wide THB R (22)

540.00 m² @ R 224/m² — R 1210.0

B.F.R. 28310.0

Accl Gst & Wery (13.1) — R 3680.0

Accl S. Rce — R 227.0

R. 32217.0

low 2.10% — R 677.0

R. 31540.0

~~82~~
08/10-24
10/10

Male

Qty - 68.67 R m³

~~82~~

08/10-24
10/10