

2nd year maintenance

24

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
New: To 3 to Harpur Mahamada Ram					
Solamoni Puro nichayilko keshar					
hole hue Tattbandh Tak.					
Agency - M/S Ram Sagar Sai fu.					
Agm No -	51(105)			2021-22	
Do. S -	28.10.2021				
Actual D.O.C -	20.10.2022				

① Restoration of Reinact -

6 x 7.00 x 0.65 x 0.30 =	8.19
8 x 5.00 x 0.90 x 0.175 =	6.30
5 x 7.00 x 0.85 x 0.100 =	3.82
7 x 02.00 x 0.75 x 0.300 =	3.15


21.46 m³

4km. — 14.38 m³

② Maintenance of earthen

Shoulder —

2 x 7.00 x 0.80 —	11.20
1 x 12.00 x 0.75 —	9.00
1 x 15.00 x 0.90 —	13.95
2 x 8.00 x 0.85 —	13.60
1 x 16.00 x 0.90 —	14.40
2 x 6.00 x 0.75 —	9.00
2 x 4.00 x 0.80 —	6.40
2 x 5.50 x 0.70 —	7.70
1 x 14.00 x 0.90 —	12.60
	<u>87.85</u>
4km. —	82.69 m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Maint. of Road Sign - Qty with this R (25) 0.245 km @ R 1077.81 / km - R 264 =					
④ Maint. of 200m & km Stone - Qty with this R (25) 0.037 km @ R 720.03 / km - R 27 =					
⑤ Cutting of Branches - Qty with this R (25) 1.10 km @ R 109.74 / km - R 110 =					
⑥ Trimming of Grasses - Qty with this R (25) 205.74 m ² @ R 2.24 / m ² - R 463 =					
⑦ White washing on parapet - Qty with this R (25) 4.50 m ² @ R 16.44 / m ² - R 74 =					
					R. 11440 =
Accl. C.R. + C. (13%) At R 14872					
Accl. S. Tre - At R 90 =					
					R. 13017 =
Less 2.10 % Below - R 273 =					
					R. 12744 =
 14/10/2024					
<u>Note</u>					
Q. No. 27.29 m ³					
 14/10/2024					