

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>3rd year Maint.</u>					
N/w: Maint. of Road from PWD Kanug Chok to Harizon tola Saidpur.					
Agency: Sri Janak Krishore Ray					
Agr. No: 69 (SBD) 2018-19					
Measurement Date:- 18/3/22					

Details —————

① Restoration of Rain
Cut —————

R.H.S	15	4.6	1.00	0.3	20.70
	10	5.75	1.10	0.3	18.98
	12	8.25	1.25	0.3	37.13
	10	3.50	0.90	0.3	9.45
	8	2.85	1.20	0.3	8.20
L.H.S	12	2.65	1.06	0.3	10.11
	16	1.74	1.33	0.3	11.10
	10	2.80	1.08	0.3	9.07
					124.74 m ³

② Maint. of Earthen Shoulder —————

R.H.S	1	20	4.25	1.10	93.50
	1	12	3.80	1.00	45.60
	1	18	6.20	1.10	122.76
	1	10	5.23	1.10	57.53
L.H.S	1	12	4.65	1.00	55.80

[illegible]