

5 yr	Maints	Work			
4th	yr	Maints	Bill		
N/Road:- 5 yrs Maints of Road					
from Thundo Panchayat					
Main Road to Kailashpur					
Village					
Agency:- MD. Shahbaz Alam					
At- Purani Bazar Jami					
Ag No:-	02	(SBD)	2018	-19	
Date of	Start	13	06	2018	
Date of	Completion	12	12	18	
Actual	Date of	Completion	25	10	2020
Date of Entry:-					
Maints	Cost	Rs	878	08	2

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of Raincuts					
Burns with soil masonry					
$6 \times 12.0 \times 0.60 \times 0.30$					$= 12.96 M^3$
$8 \times 8.0 \times 0.45 \times 0.30$					$= 8.64 M^3$
$10 \times 15.0 \times 0.75 \times 0.30$					$= 33.75 M^3$
$9 \times 12.0 \times 0.60 \times 0.30$					$= 19.44 M^3$
$7 \times 6.0 \times 0.45 \times 0.30$					$= 5.67 M^3$
					$80.46 M^3$
2. Making up of Burns/					
Shoulder striping excup					
soil from the shoulder					
surface to achieve					
level					

$6 \times 30.0 \times 1.20$	$= 216.00 M^2$
$8 \times 19.0 \times 0.90$	$= 136.80 M^2$
$06 \times 15.0 \times 0.60$	$= 18.00 M^2$
$08 \times 13.0 \times 0.45$	$= 46.80 M^2$
	$417.60 M^2$

3. Repair of pot holes filled	
with > 5mm WBM x 1.25	
$6 \times 12.0 \times 0.15$	$= 10.80 M^2$
$8 \times 6.0 \times 0.30$	$= 14.40 M^2$
$10 \times 3.0 \times 0.45$	$= 13.50 M^2$
$12 \times 5.0 \times 0.30$	$= 18.00 M^2$
$5 \times 9.0 \times 0.30$	$= 13.50 M^2$
	$70.20 M^2$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
10 White Washing of Parapet					
12 Walls of CD Work					
Tree Trunks					
TOP - 3x 2x6.15 x 0.40					14.76 M ²
and Parapet 3x 4x0.40 x 0.50					5.76 M ²
Inner Side 3x 2x6.15 x 0.60					22.14 M ²
					42.66 M ²

4th yr Maults Poll					
ABSTRACTS OF COST					
1. Restoration of Raincuts					
Qty vide 4 No 21 in mm ³					
80.46 M ³					
@ Rs 352221/M ³					Rs 2838920
2. Making up of Berms/Shoulder					
stripping excess Soil					
from the Shoulder Surface					
to achieve level					
Qty vide 21 in mm ³					
417.60 M ³					
@ Rs 51271/M ³					Rs 215942
					Rs 4998320

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			BIP R 49 983	2 W	
3 Repair of Potholes					
filled with 75mm WBM					
1.25					
Qty vide PNO 21 in TMB					
		70.20 M ²			
Q R 199 = 73 / M ²				R 14021 =	
4(ii) Patch repair over					
15.5 Potholes with 20 mm					
premix Surfacing					
material					
Qty vide PNO 22 in TMB					
		70.20 M ²			
Q R 259 = 42 / M ²				R 18211 =	
5 Maults of H.P. Culvert					
7 Qty vide PNO 22 in TMB					
		70.20 M ²		345	
Q R 1100 = 35 / each				R 3313 =	
6 Maults of Road Bridge					
8 Qty vide PNO 22 in TMB					
		0.22 KM			
Q R 1067 = 244 / KM				R 235 =	
7 Maults of 200 M 2 KM Stone					
10 Qty vide PNO 22 in TMB					
		0.27 KM			
Q R 570 = 271 / KM				R 154 = W	

R 85917 = W

Continuation

28/7/20 Continuation