

5th year maintenance

68

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: No on far to 19 to D.K. in Ray Tola Talu					
2. Name of Agency: Ananta Kumar					
					anal
3. Agreement No: 102/SBD/2018-19					
4. Actual date of completion: 01.08.2019					
measurement as below					
① Restoration of drain cut					
1 with 50% slope					
1x 30.0 x 1.0 x 0.30					9.0
1x 5.20 x 0.90 x 0.28					1.310
2x 20.60 x 0.80 x 0.30					9.888
1x 5.0 x 0.70 x 0.30					1.05
2x 10.0 x 0.65 x 0.32					4.16
3x 5.0 x 0.60 x 0.30					2.70
2x 20.0 x 0.50 x 0.30					6.0
1x 1.10 x 0.50 x 0.28					0.154
					Qty = 34.262 m ³
					Say Qty = 34.17 m ³
② maintenance of earthen shoulder					
1x 20.50 x 0.90					18.45
1x 30.0 x 1.0					30.0
2x 30.0 x 0.90					54.0
1x 20.60 x 0.70					14.42
2x 30.0 x 0.65					39.0

Continuation

C.O. Qty = 155.87 m³

P.T.O.

[illegible]

material statement

(i) Gravel	62.65 m ³
(ii) Bitumen 590	$\frac{168.054}{1.25} = 138.49$
(iii) Stone chips	$\frac{2.69}{2.271}$

1m				
3.09.2024				
JE	opening balance bitumen			
	= 168.064 kg	note mb		
		Page (66)		
	consumed bitumen			
	= 168.059 kg	note mb		
		P-73		
	Rest balance bitumen			
	= 168.064 kg			
	- 168.059 kg			
	= 0.01 kg			

Continuation