

4th year Maintenance

Sch. XLV-Form No.134

47

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance of road from L.039 to Machhlar under MINSY (se)					
Agency - Sri Sunil Kumar					
Agreement No - 60 SBD/2018-19					
Date of start - 10/01/2019					
Date of completion - 09/10/2019					
Actual date of completion - 08/10/2019					
4 th year Maintenance } 09/10/2022 to period } 08/10/2023					

① Restoration of Rain cuts

1 X	7.50	X	1.10	X	0.25 =	2.06 m ³
1 X	9.40	X	1.15	X	0.30 =	5.10 m ³
1 X	7.20	X	1.20	X	0.25 =	2.16 m ³
2 X	10.40	X	1.25	X	0.30 =	7.50 m ³
1 X	5.40	X	0.90	X	0.30 =	1.35 m ³
1 X	7.40	X	1.10	X	0.30 =	2.31 m ³
2 X	8.50	X	1.25	X	0.25 =	5.31 m ³
2 X	6.50	X	1.25	X	0.25 =	4.06 m ³
2 X	7.50	X	1.15	X	0.30 =	5.17 m ³
2 X	11.40	X	1.20	X	0.25 =	6.60 m ³
						<u>41.62 m³</u>

② Maintenance of earthen shoulder

2	X	5.50	X	1.10 =	13.20 ft
1	X	6.25	X	0.90 =	5.62 ft
2	X	11.40	X	1.25 =	27.50 ft
Continuation					<u>46.32 ft</u>

Particulars	Details of actual measurement			Contents of area
	No.	L.	B. D.	
			B. F -	46.32M ^L
1	X	6.10	X 1.20 =	7.68M ^L
2	X	7.10	X 1.15 =	16.10M ^L
2	X	6.10	X 1.25 =	15.10M ^L
1	X	9.10	X 1.20 =	10.80M ^L
1	X	6.50	X 1.10 =	7.15M ^L
1	X	7.50	X 1.20 =	9.10M ^L
2	X	10.50	X 1.25 =	26.25M ^L
2	X	12.10	X 1.25 =	30.40M ^L
2	X	8.10	X 1.15 =	18.40M ^L
2	X	7.10	X 1.20 =	17.04M ^L
3	X	5.10	X 0.85 =	12.75M ^L
				216.49M ²

③ Maintenance of bituminous surface road

① Repair to Pot holes

1	X	2.50	X 1.50 =	3.75M ^L
3	X	2.00	X 1.25 =	7.50M ^L
1	X	4.00	X 2.00 =	8.00M ^L
2	X	3.00	X 1.50 =	9.00M ^L
2	X	4.50	X 1.50 =	13.50M ^L
3	X	3.50	X 1.60 =	16.80M ^L
3	X	3.05	X 1.50 =	13.72M ^L
				72.27M ²

(ii) Maintenance of WBM road

Q- Same as above = 72.27M²

Abstract of cost

50

Sch. XLV-Form No.134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	D.
① Restoration of Rainceet				
Q-VTMBP 47① =		41.62 m ²		
c R 352.21/m ² R -				1465920
② Maintenance of earthen Shoulder				
Q-VTMBP 47② =		216.49 m ²		
P 49④ =		130.34 m ²		
		346.83 m ²		
c R 51.90/m ² R -				1866020
③ Maintenance of Bituminous Surface road				
① Repair to pot hole				
Q-VTMBP 48③ =		72.27 m ²		
c R 284.20/m ² R -				2053920
(ii) Maintenance of WBM road				
Q-VTMBP 48③ =		72.27 m ²		
c R 374.61/m ² R -				2707320
(iii) Patch repair				
Q-VTMBP 48③ =		72.27 m ²		
c R 268.75/m ² R -				1942320
④ Maintenance of H.P. culvert				
Q-VTMBP 49⑤ =		1 May		
c R 1104=35/each R -				110420
⑤ White washing on parapet				
Q-VTMBP 49⑤ =		14.46 m ²		
c R 16.05/m ² R -				23220

Continuation

10103020

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ cutting of branches of trees					
Q-VINB/49⑥ = 4 Nos					
e h 104.48/each h					41829
⑦ cutting of shrubs					
Q-VINB/49⑦ = 9 Nos					
e h 6.42/each h					5820
⑧ Trimming of grass					
Q-VINB/49⑧ = 390.00 h					
e h 2.14/11 h					83520
⑨ Maintenance of road sign					
Q-VINB/49⑨ = 2.100 Km					
e h 1067.44/kmh					224200

⑩ Maintenance of 200 m stone

Q-VINB/49⑩ = 0.139 Km

e h 729.97/kmh 10/20

h 104684=0

Less 10% below → 10468=00

h 94216=00

Burn
09/10/23

Burn
09/10/23

cap
Vijayare
12/10/23 AS