

1

Name of work -
 Situation of work -
 Agency by which work is executed -
 Date of measurement -
 No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road →: Baedila R.E.O					
road to murgia Tola Bathan					
Hote Hua to murgia Tola					
Dasu Raut Tola Tak (W/B)					
Name of Agency →: m/s Ravi construct					
At - Adhiwakta Nagar, Gwalior					
length →: 2.300 Km					
Agreement No →: 41/M.B.D/2017-18					
Estimated cost →: 1,87,62,154 = 00					
Date of Commencement →: 11/06/2017					
Date of Completion →: 10/06/2018					
Date of measurement →: 25/5/2018					
(1/4) Reference Pillar as per					
Standard Data Book					
@ 4 per Km do-do Elt					
					= 10.00 Nos
(2/5) Clearing and grubbing					
road including do-					
do — do — do — Elt					
1x 30.00 x 4.00 =					120.00m ²
3x 30.00 x 4.00 =					360.00m ²
10x 30.00 x 4.00 =					1200.00m ²

Continuation

Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
<u>2nd Year Maintenance</u>					
Name of work -	Bardila RED road				
	to Murgiya Tola Bather				
	Hole Lura to Murgiya Tola				
	Daku Sant Tola Tak (W.B)				
Agency:-	Ravi Construction				
	Adhiwakta Nagar Sopalganj				
Agreement No -	41MBD/WB 2017-18				
Dated Commitment -	11-06-2017				
Date of Completion -	10-06-2018				
Actual date of Completion -	10-09-2019.				

① Restoration of drain					
Cuts with soil - as					
per tech. spec.					
4	8.0	0.9	0.30	8.64 m ³	
6	9.0	0.80	0.30	12.96 m ³	
5	7.5	0.80	0.30	9.0 m ³	
6	8.5	0.90	0.30	13.77 m ³	
1	7.0	0.80	0.30	1.68 m ³	
				46.05 m ³	
② Making up berms/					
shoulder, stripping					
excess soil from					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
① Restoration of side cuts - - - tech. sp.					
46.05 m ³ vide TMB Page (58)					
@ Rs 301299/m ³ - 4					1390720
② Making up Berms/Shoulder - - - tech. sp.					
219.10 m ³ vide TMB Page (59)					
@ Rs 47224/m ³ - 4					1039020
③ Repair of Pot holes with 75 mm Br. - - - tech. sp.					
2.69 m ³ vide TMB Page (59)					
@ Rs 12191 = 48600					3279520
④ Patch repair over Pot holes - - - tech. sp.					
45.8 m ³ vide TMB Page (59)					
@ Rs 24982/m ³ - 4					1130920
⑤ Patch repair over bituminous surface - - - tech. sp.					
45.25 m ³ vide TMB Page (60)					
@ Rs 32593/m ³ - 4					1474820
⑥ Maintenance of H.P. Culvert - - - tech. sp.					
3.0 Nos. vide TMB Page (60)					
@ Rs 84696/ea - 4					254120
Continuation					Rs 8564520

Continuation