

4th year maintenance Bill

30

Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
N/R-	Repair Road from				
	Daryapur Harbathpur				
	to paswan Tala manda				
	Tala under mngsy (sc)				
Agency-	Sri Ravindra Kumar				
	Bhagalpur				
Agg No-	34-SBO-2018/19.				
A/D/O/C-	06-01-2019				
Period-	07-01-22 To				
	06-01-23				
Rate-	10% below				

① Restoration of rain cuts					
7 x 4.00 x	$\frac{0.90 + 0.80}{2}$	x 0.30			7.14 m ³
8 x 2.50 x	$\frac{1.20 + 1.20}{2}$	x 0.30			7.20 "
6 x 3.00 x	$\frac{1.20 + 0.80}{2}$	x 0.30			5.40 "
10 x 3.50 x	$\frac{1.20 + 1.10}{2}$	x 0.30			12.08 "
5 x 2.50 x	$\frac{1.14 + 1.00}{2}$	x 0.25			3.34
					35.16

② making up of berms					
& shoulders					
9 x 4.00 x	1.12				40.32 m ²
5 x 5.00 x	1.00				25.00 "
6 x 6.00 x	1.00				36.00 "
10 x 4.00 x	1.74				69.60 "
9 x 3.50 x	1.10				34.50 "

(Continuation)

31

30

Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
0.07 K.m wide P.No (31)					
@ 1067.49/K.m					75.00
(4) maintenance of 200m					
8 K.m					
0.08 K.m wide P.No (31)					
@ 576.34/K.m					46.00
					22652.00
less 107.60/0					2265.00
					20,387.00
Signature	08/08/23	Signature	08/08/23		

materials Consumption
 Earth- 55.80 m³

~~Signature~~
 08/08/23
 J.E

(Continuation)