

1st year maintenance bill

16

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
N/w:- mukhya path Dabarpur					
to Harizan talg					
mogimpur under					
mmgsy (SC)					
Agency:- Ashish Kumar					
Agg No- 41/530/2020-21.					
A/d/O/c- 15.10.2021.					
Period- 16.10.2021 to					
15.10.2022					
Rate- 0.11 % below as per Agg					
Measurement Record					

1/ Restoration of rain cuts

$8 \times 2.50 \times \left(\frac{1.00 + 0.60}{2} \right) \times 0.30$	4.80m ²
$9 \times 2.20 \times \left(\frac{1.00 + 0.80}{2} \right) \times 0.30$	5.35"
$7 \times 2.00 \times \left(\frac{1.20 + 1.20}{2} \right) \times 0.30$	5.04"
$6 \times 2.80 \times \left(\frac{1.10 + 0.90}{2} \right) \times 0.30$	5.04"
$8 \times 2.00 \times \left(\frac{1.10 + 0.95}{2} \right) \times 0.30$	4.92"
	25.15m ²

2/ making up of Berms shoulder

$10 \times 3.10 \times 0.85$	26.35m ²
$8 \times 3.30 \times 1.05$	27.72"
$12 \times 3.50 \times 1.10$	46.20"
$10 \times 2.50 \times 0.85$	21.25"

(Continuation)

Sch. XLV-Form No. 134

[illegible]

materials Consumption
Earth- 46.15 m^3

191922

(Continuation)