

Sch: XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
2nd year maintenance					
N/A - PMAS Habibpur to					
Nadafoli taluk.					
Agency - Suraj Kumar					
Ag No - 39 L.S.B.D / 18-19					
Actual date of comp - 20/01/2021					
Date of measurement -					

① Restoration of rain cuts - do -

$$2 \times 4.0 \times 1.0 \times 0.25 = 2.00 \text{ m}^3$$

$$4 \times 3.0 \times 0.90 \times 0.25 = 2.70 \text{ m}^3$$

$$2 \times 3.0 \times 0.90 \times 0.25 = 1.35$$

$$9.05 \text{ m}^3$$

② Making of berms/shoulder -

$$2 \times 4 \times 6.0 \times 1.0 = 48.00 \text{ m}^2$$

$$2 \times 2 \times 7.0 \times 0.90 = 25.20 \text{ m}^2$$

$$2 \times 3 \times 5.0 \times 0.90 = 27.00 \text{ m}^2$$

$$2 \times 2 \times 4.0 \times 1.0 = 16.00 \text{ m}^2$$

$$2 \times 3 \times 5.0 \times 0.80 = 19.20$$

$$135.40$$

$$\text{Ans} - 135.40 \text{ m}^2$$

③ Patch repair over bituminous surface - do -

(Continuation)

Sch. XLV- Form No. 134

Sch. XLV- Form No. 134					Contents or area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
① Restoration of rain cuts - 9.05 m ³ vide P. No (34)					
@ Rs. 365.25/m ³ -				3306.25	
② Making up of beams/shoulder 135.0 m ² vide P. No (34)					
@ Rs. 54.16 / -				7312.50	
③ Patch repair - 7.20 m ² vide P. No (35)					
7.20 m ² @ 185.88 / -				1338.34	
④ Main of H. P culvert 1 Nox vide P. No (35)					
⑤ Main. of road sign. 0.65 Km vide P. No (35)					
@ 1087.62 / -				54.00	
⑥ Main. of 200 m x 8 Km stone. 0.06 Km vide P. No (35)					
@ 582.10 / -				35.00	
⑦ White washing of Parapet wall of CD work 20.64 m ² vide P. No (35)					
@ Rs. 16.48 / -				340.00	
				13517.50	
Less 10% below -				1352.00	
				12165.50	

(Continuation)

For