

3rd year Maintenance bill

71

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:— Routine maintenance work for 3rd year of road from 1031 Chhote Lal Singh ke Bagicha to Naro Muras (Nuwada zil(a) samrat under mmwy (SC) at block Kabisarai					
M/Agency— Nadari Construction Pvt. Ltd.					
Ass. MO— 26/08/2019-20					
Actual date of completion—					12.06.21

Date of measurement— 10.08.21

Items of work

① Restoration of road cuts/berms with soil—					
6 x 2.65m x 1.45m x 0.30m = 6.91m ³					
8 x 2.30m x 1.20m x 0.30m = 6.62m ³					
12 x 2.85m x 1.40m x 0.30m = 14.36m ³					
10 x 3.20m x 1.50m x 0.30m = 14.40m ³					
15 x 2.70m x 1.65m x 0.30m = 20.04m ³					
12 x 3.00m x 1.35m x 0.30m = 14.58m ³					
7 x 2.55m x 1.40m x 0.30m = 7.49m ³					
15 x 2.10m x 1.55m x 0.30m = 21.62m ³					
12 x 2.85m x 1.60m x 0.30m = 16.41m ³					
Total =					122.43m ³

Continuation



Continuation