

4th year maintenance Bill

Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
N/wt — const ⁿ of road from					
Amba Salpazaya path to horizon					
Jala (Modha) MMGSX (SC)					
Aggr Agency — Sri Ganesh Enterprises,					
Bhagalpur —					
Aggr. No. — SBD/23/18-19					
D/O/W — 10/8/18					
D/O/C — 9/05/19					
A/D/O/C — 16/02/19					
Rate — 10% below as per Aggr.					
Period — 17/02/22 to 16/02/23					

Measurement

1) Restoration of damaged of shoulder

do — do —

$$6 \times 8.5 \times 0.9 \times 0.2 = 9.18$$

$$5 \times 6.5 \times 0.65 \times 0.25 = 5.28$$

$$6 \times 6.9 \times 1.2 \times 0.3 = 14.90$$

$$7 \times 4.8 \times 0.85 \times 0.25 = 7.14$$

$$\text{Qty} = 36.51 \text{ m}^3$$

2) Making up berms/shoulder shapping

do — do — all comp job

$$5 \times 5.5 \times 1.05 = 28.88$$

$$8 \times 7.0 \times 1.1 = 61.6$$

$$6 \times 6.4 \times 1.0 = 38.40$$

maternal

1) Earth - 36.51 m^3

SV
15/07/23
J.E