

1st year of maintenance work

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Reo Road se					
Changel siwan via Lakshminagar					
Tola.					
Name of Agency - Suresh Ray.					
Aggr no mmcsy/srd/57/2012-20					
Date of Start - 20-3-2020					
Date of completion - 19-3-2021					

① Restoration of Rain cut

$2 \times 6.5 \times 1.65 \times 0.30 = 6.435$	
$4 \times 8.15 \times 1.55 \times 0.30 = 15.15$	
$3 \times 5.25 \times 1.61 \times 0.30 = 7.60$	
$7 \times 9.65 \times 1.58 \times 0.30 = 32.01$	
$6 \times 11.28 \times 1.66 \times 0.30 = 33.70$	
$4 \times 8.75 \times 1.59 \times 0.30 = 22.89$	16.69
$6 \times 7.85 \times 1.62 \times 0.30 = 22.80$	
$5 \times 14.18 \times 1.70 \times 0.30 = 36.15$	
	$= 170.62/m^3$
2. maintenance of Earthen shoulder	
$2 \times 4 \times 30.0 \times 1.00 = 240.00$	
$2 \times 5 \times 30.0 \times 0.800 = 240.00$	

Continuation

Sch. XLV-Form No. 134

1312162

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ Patch Repair on mib seal surface Type B vide TMBP-78 - 49.35/m ² @ 223.38/m ² = 11024=00					
⑤ Maintenance of culvert vide TMBP-78 - 8.00/NO @ 1137.48/m ² = 9099=00					
⑥ Maintenance of Road Sign vide TMBP-78 - 3.398/KM @ 1099.46/KM = 3736=00					
⑦ Maintenance of 200m and km stone vide TMBP-79 - 0.408/KM @ 740.88 = 302=00					
⑧ Cutting of Branch of Tree vide TMBP-79 - 21/NO @ 107.62/NO = 302=00 2260=00					
⑨ Trimming of grass vide TMBP-79 - 1512/m ² @ 2.21/m ² = 3342=00 160979=00 Less 10% below - 16098=00 144881=00					

23
15/6/24
00

Continuation