

2nd Year maintenance

69

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: S023 kabn from to north malanga					
2. Agency: Ramanand Thakur					
3. Agreement no: 01/SB0/2022-23					
4. Actual dt. of completion: 21.07.2022					
Measurement as below -					
Item ① Restoration of rain cuts with 80% curb					
	1	30.0	0.45	0.30	= 4.050
	1	30.0	0.45 + 0.60	0.30	= 4.725
	1	30.0	0.50	0.30	= 4.50
	1	30.0	0.48	0.30	= 4.32
	3	30.0	0.45	0.30	= 12.15
	4	30.0	0.42	0.30	= 15.12
	2	30.0	0.50	0.30	= 9.0
	4	30.0	0.48	0.30	= 17.28
	1	30.0	0.42	0.30	= 3.78
	3	30.0	0.52	0.30	= 13.52
	1	20.50	0.40	0.30	= 2.46
					Qty = 90.885m
					Qty = 90.885m
② maintenance of earthen shoulder - 1/2					
	5	30.0	0.45		= 67.50
	1	30.0	0.40		= 12.00
	2	30.0	0.48		= 28.80
	3	30.0	0.42		= 37.80

Qty = 146.10m

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B.P.B	154280=00
Add	1%	Labour			1543=00
Add	12%	G.S.T			18514=00
				B	174337=00

Rams

11.07.2024

J-E

Cell
11/17/2024
J-E

material statement

(i)	Sand	—	166.62m ³
(ii)	Bitumen 50	—	0.148MT
(iii)	Stone chips	—	1.893m ³

Rams

11.07.2024

J-E

Cell
11/17/2024
J-E

Continuation