

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/11:-	Chirpili	Lala Bigha			
	To	Harna	Pasi	Tota	Vin
	Passwara				
Agency:-	Jai Kumar				
Agreement No:-	14 SDD/2020-21				
Date of Commencement:-	17/07/2020				
Date of Completion:-	16/07/2021				
Actual Date of Completion:-	04/05/2022				

Record Measurement

① Restoration of Rim City
With Soil - do -

$$6 \times 30 \times 0.90 \times 0.250 = 40.50$$

$$1 \times 10 \times 0.92 \times 0.300 = 2.76$$

$$1 \times 30 \times 0.85 \times 0.30 = 7.65$$

$$2 \times 30 \times 1.00 \times 0.30 = 18.00$$

$$4 \times 18 \times 0.60 \times 0.200 = 8.64$$

$$1 \times 30 \times 0.80 \times 0.300 = 7.20$$

$$1 \times 16.00 \times 0.50 \times 0.200 = 1.60$$

$$T. Qty = 86.35 m^3$$

② Making up of beam/
Shoulder, stripping excess
soil from the shoulder - do -

$$4 \times 30.00 \times 1.10 = 132.00$$

$$1 \times 25.00 \times 1.00 = 25.00$$

$$1 \times 30.00 \times 1.25 = 37.50$$

$$3 \times 30.00 \times 0.85 = 76.50$$

$$1 \times 21.00 \times 0.80 = 16.80$$


$$1 \times 30.00 \times 1.20 = 36.00$$


$$C/F = 323.80 m^2$$

Continuation

Material Statement

(1)	Earthwork	—	123.00m ³
(2)	Sand	—	0.40m ³
(3)	Stone Chips	—	3.6m ³
(4)	Bitumen Emulsion (RS1)	—	33.00kg
(5)	Bitumen (S90)	—	269.00kg

 06/05/24
J.E.

 06/05/24
AC-

Scanned with CamScanner